

96-D Allen Boulevard Farmingdale, New York 11735-5626 USA Tel. +1 (631) 293-8944 Fax +1 (631) 293-8956 e-mail: info@govmark.com

Page 1

120001100112	33/2013  Complete	ed: 12/13/2013	Letter: B4	CJ	<b>P.O.</b> #:	17324			Test Report	t <b>#:</b>	2-99882	-0-04
Client's Identificatio	Style: 20oz Viny Sample ID #150		with OSNA Back f Fabric: Comme				otton B	acking	g. Weight: 20c	oz Linear Yd	. Color:	
ł	Tested For: Mark Rain				Key Test: FTM 5100.1/ASTM I							135
٥	Roysons Corp. 40 Vanderhoof Av Rockaway, NJ 07			, ,					3)-625-5570 3)-625-5917	Ext:	124	
Category:	Break/Tensile	Sì	pecifier: AST	'M F	793				PC:	24H		
TEST PERFORMED: Federal Test Standard 191A Method 5100.1 - Strength and Elongation, Breaking of Woven Cloth; Grab Method												
RESULTS:		Machine Direction			s Mach	ine						
Specimen #		(lbs)		(lbs								
1 2 3 4 5		112 113 118 119 118		12 12 12 12 12	7 9 7 8							
Avq		116		12	 7							
CLASSIFICA Characteri Categor		cial Service Machine Di (lbs	ability rection C		Machin	ne Dii			of Wallcov	rering by	Durabil	ity
IV	 I	Minimur			Minim							
V	III	Minimur Minimur			Minim							
CONCLUSION	: Based on th	ne above Resi	ılts and Clas	sifi	cation	Crite	eria,	the	item teste	ed:		
For Cat	egory IV Type egory V Type egory VI Type	II: [x]		] D	oes no	t comp	oly					
	ION: I certif											e
A	MU		MS. PH	YLL	SPET	TIT						
AUTHORIZED THE GOVMAR	SIGNATURE K ORGANIZATION	N, INC. / ec	/gb	Page	1 of :	1)		JAN	2 4 2014	-		